
40 C.F.R. § 63.7793

What work practice standards must I meet?

- (a) You must meet each work practice limit in table 1 to this subpart that applies to you.
- (b) For unplanned bleeder valve openings on a new and existing blast furnace, you must meet each work practice standard listed in paragraphs (b)(1) through (3) of this section.
 - (1) Develop and operate according to a “Slip Avoidance Plan” to minimize slips and submit it to EPA for approval;
 - (2) Install devices to continuously measure/monitor material levels in the furnace (*i.e.*, stockline), at a minimum of three locations, with alarms to inform operators of static (*i.e.*, not moving) stockline conditions which increase the likelihood of slips; and
 - (3) Install and use instruments on the furnace to monitor temperature and pressure to help determine when a slip is likely to occur.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)