

40 C.F.R. § 57.501

General requirements.

- (a) Each NSO shall require the smelter owner to use such control measures as may be necessary to ensure that the smelter's fugitive emissions do not result in violations of the NAAQS for SO₂ in the smelter's DLA.

This document is only available to subscribers. Please log in or purchase access.

[Purchase Login](#)