

40 C.F.R. § 60.1450

How must I monitor opacity for air curtain incinerators that burn 100 percent yard waste?

(a) Use EPA Reference Method 9 in appendix A of this part to determine compliance with the opacity limit.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)