

## 40 C.F.R. § 60.2916

---

### What operating limits must I meet and by when?

---

(a) If you use a wet scrubber to comply with the emission limitations, you must establish operating limits for four operating parameters (as specified in table 2 of this subpart) as described in paragraphs (a)(1) through (4) of this section during the initial performance test.

(1) Maximum charge rate, calculated using one of the two different procedures in paragraphs (a)(1)(i) or (ii) of this section, as appropriate.

This document is only available to subscribers. Please log in or purchase access.

[Purchase Login](#)