
40 C.F.R. § 60.2944

What operating parameter monitoring equipment must I install, and what operating parameters must I monitor?

- (a) If you are using a wet scrubber to comply with the emission limitations under § 60.2915, you must install, calibrate (to manufacturers' specifications), maintain, and operate devices (or establish methods) for monitoring the value of the operating parameters used to determine compliance with the operating limits listed in table 2 of this subpart. These devices (or methods) must measure and record the values for these operating parameters at the frequencies indicated in table 2 of this subpart at all times.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)