

## 40 C.F.R. § 60.2972

---

### How must I monitor opacity for air curtain incinerators that burn only wood waste, clean lumber, and yard waste?

---

- (a) Use Method 9 of appendix A of this part to determine compliance with the opacity limitation.
- (b) Conduct an initial test for opacity as specified in § 60.8.

This document is only available to subscribers. Please log in or purchase access.

[Purchase Login](#)