

## 40 C.F.R. § 60.403

---

### Monitoring of emissions and operations.

---

- (a) Any owner or operator subject to the provisions of this subpart shall install, calibrate, maintain, and operate a continuous monitoring system, except as provided in paragraphs (b) and (c) of this section, to monitor and record the opacity of the gases discharged into the atmosphere from any phosphate rock dryer, calciner, or grinder. The span of this system shall be set at 40-percent opacity.
- (b) For ground phosphate rock storage and handling systems, continuous monitoring systems for measuring opacity are not required.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)