

40 C.F.R. § 60.4855

How do I establish operating limits if I do not use a wet scrubber, fabric filter, electrostatic precipitator, or activated carbon injection, or if I limit emissions in some other manner, to comply with the emission limits?

If you use an air pollution control device other than a wet scrubber, fabric filter, electrostatic precipitator, or activated carbon injection, or limit emissions in some other manner (*e.g.*, materials balance) to comply with the emission limits in § 60.4845, you must meet the requirements in paragraphs (a) and (b) of this section.

- (a) Meet the applicable operating limits and requirements in § 60.4850, and establish applicable operating limits according to § 60.4870.
- (b) Petition the Administrator for specific operating parameters, operating limits, and averaging periods to be established during the initial performance test and to be monitored continuously thereafter.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)