

40 C.F.R. § 61.142

Standard for asbestos mills.

- (a) Each owner or operator of an asbestos mill shall either discharge no visible emissions to the outside air from that asbestos mill, including fugitive sources, or use the methods specified by § 61.152 to clean emissions containing particulate asbestos material before they escape to, or are vented to, the outside air.
- (b) Each owner or operator of an asbestos mill shall meet the following requirements:
- (1) Monitor each potential source of asbestos emissions from any part of the mill facility, including air cleaning devices, process equipment, and buildings that house equipment for material processing and handling, at least once each day, during daylight hours, for visible emissions to the outside air during periods of operation. The monitoring shall be by visual observation of at least 15 seconds duration per source of emissions.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)