

## 40 C.F.R. § 1065.315

---

### Pressure, temperature, and dewpoint calibration.

---

(a) Calibrate instruments for measuring pressure, temperature, and dewpoint upon initial installation. Follow the instrument manufacturer's instructions and use good engineering judgment to repeat the calibration, as follows:

(1) *Pressure.* We recommend temperature-compensated, digital-pneumatic, or deadweight pressure calibrators, with data-logging capabilities to minimize transcription errors. We recommend using calibration reference quantities that are NIST-traceable within  $\pm 0.5\%$  uncertainty.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)