

## 40 C.F.R. § 440.148

---

### Best Management Practices (BMP).

---

The following best management practices are specific requirements which shall be included in each NPDES permit for all mining operations regulated under this subpart to the greatest extent applicable in each such mining operation.

- (a) *Surface water diversion*: The flow of surface waters into the plant site shall be interrupted and these waters diverted around and away from incursion into the plant site.

This document is only available to subscribers. Please log in or purchase access.

[Purchase Login](#)