

## 40 C.F.R. § 761.302

---

### Proportion of the total surface area to sample.

---

(a) *Large nearly flat surfaces.* Divide the entire surface into approximately 1 meter square portions and mark the portions so that they are clearly identified. Determine the sample location in each portion as directed in § 761.304.

(1) For large nearly flat surfaces contaminated by a single source of PCBs with a uniform concentration, assign each 1 meter square surface a unique sequential number.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)