

40 C.F.R. § 761.369

Pre-cleaning the surface.

If visible PCB-containing liquid is present on the surface to be cleaned, thoroughly wipe or mop the entire surface with absorbent paper or cloth until no liquid is visible on the surface.

This document is only available to subscribers. Please log in or purchase access.

Purchase Login