

40 C.F.R. § 240.208-3

Recommended procedures: Operations.

- (a) The furnace operator should visually observe the quality of the bottom ash at least twice per shift and record in the operating log the estimated percentage of unburned combustibles.

This document is only available to subscribers. Please log in or purchase access.

[Purchase Login](#)