

40 C.F.R. § 265.381

Closure.

At closure, the owner or operator must remove all hazardous waste and hazardous waste residues (including, but not limited to, ash) from the thermal treatment process or equipment.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)