

## 40 C.F.R. § 98.112

---

### GHGs to report.

---

You must report:

- (a) Process CO<sub>2</sub> emissions from each electric arc furnace (EAF) used for the production of any ferroalloy listed in § 98.110, and process CH<sub>4</sub> emissions from each EAF that is used for the production of any ferroalloy listed in Table K-1 to subpart K.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)