

40 C.F.R. § 98.194

Monitoring and QA/QC requirements.

- (a) You must determine the total quantity of each type of lime product that is produced and each calcined byproduct or waste (such as lime kiln dust) that is sold. The quantities of each should be directly measured monthly with the same plant instruments used for accounting purposes, including but not limited to, calibrated weigh feeders, rail or truck scales, and barge measurements. The direct measurements of each lime product shall be reconciled annually with the difference in the beginning of and end of year inventories for these products, when measurements represent lime sold.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)