

40 C.F.R. § 98.284

Monitoring and QA/QC requirements.

- (a) You must measure your consumption of petroleum coke using plant instruments used for accounting purposes including direct measurement weighing the petroleum coke fed into your process (by belt scales or a similar device) or through the use of purchase records.

This document is only available to subscribers. Please log in or purchase access.

[Purchase Login](#)