

## 40 C.F.R. § 98.74

---

### Monitoring and QA/QC requirements.

---

- (a) You must continuously measure the quantity of gaseous or liquid feedstock consumed using a flow meter. The quantity of solid feedstock consumed can be obtained from company records and aggregated on a monthly basis.
- (b) You must document the procedures used to ensure the accuracy of the estimates of feedstock consumption.
- (c) You must determine monthly carbon contents and the average molecular weight of each feedstock consumed from reports from your supplier. As an alternative to using supplier information on carbon contents, you can also collect a sample of each feedstock on a monthly basis and analyze the carbon content and molecular weight of the fuel using any of the following methods listed in paragraphs (c)(1) through (c)(8) of this section, as applicable.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)