

## 40 C.F.R. § 62.15380

---

### How must I monitor opacity for air curtain incinerators that burn 100 percent yard waste?

---

- (a) Use EPA Reference Method 9 in appendix A of 40 CFR part 60 to determine compliance with the opacity limit.

This document is only available to subscribers. Please log in or purchase access.

[Purchase Login](#)