
40 C.F.R. § 63.1442

What parts of my plant does this subpart cover?

- (a) This subpart applies to each new and existing affected source at your primary copper smelter. The affected sources are each copper concentrate dryer, each smelting vessel, each slag cleaning vessel, each copper converter department, each anode refining department, process fugitive emission sources (i.e., roofline vents) from smelting vessels, slag cleaning vessels, copper converter department and anode refining department, each bypass stack, and the entire group of fugitive dust sources, as defined in § 63.1459.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)