

## 40 C.F.R. § 63.5715

---

### What operating limits must I meet?

---

- (a) For open molding operations on which you use a thermal oxidizer as an add-on control device, you must meet the operating limits specified in Table 4 to this subpart that apply to the emission capture system and thermal oxidizer. You must establish the operating limits during the performance test according to the procedures in § 63.5725. You must meet the operating limits at all times after you establish them.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)