

## 40 C.F.R. § 63.6004

---

### How do I demonstrate continuous compliance with the emission limits for tire production affected sources?

---

- (a) You must demonstrate continuous compliance with each applicable limit in Table 1 to this subpart using the methods specified in Table 10 to this subpart.
- (b) You must report each instance in which you did not meet an emission limit in Table 1 to this subpart. You must also report each instance in which you did not meet the applicable requirements in Table 10 to this subpart. These instances are deviations from the emission limits in this subpart. The deviations must be reported in accordance with the requirements in § 63.6010(e).

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)