

40 C.F.R. § 63.6005

How do I monitor and collect data to demonstrate continuous compliance with the emission limits for tire cord production affected sources?

- (a) You must monitor and collect data to demonstrate continuous compliance with the emission limits for tire cord production affected sources as specified in table 11 to this subpart.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)