

40 C.F.R. § 63.6007

How do I monitor and collect data to demonstrate continuous compliance with the emission limitations for puncture sealant application affected sources?

- (a) You must monitor and collect data to demonstrate continuous compliance with the emission limitations for puncture sealant application affected sources as specified in table 13 to this subpart.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)