

40 C.F.R. § 63.6008

How do I demonstrate continuous compliance with the emission limitations for puncture sealant application affected sources?

- (a) You must demonstrate continuous compliance with each applicable emission limitation in tables 3 and 4 to this subpart using the methods specified in Table 14 to this subpart.

This document is only available to subscribers. Please log in or purchase access.

[Purchase Login](#)