

40 C.F.R. § 63.7114

How do I demonstrate initial compliance with the emission limitations standard?

- (a) You must demonstrate initial compliance with each emission limit in Table 1 to this subpart that applies to you, according to Table 4 to this subpart. For existing lime kilns and their associated coolers, you may perform VE measurements in accordance with EPA Method 9 of appendix A to part 60 in lieu of installing a COMS or PM detector if any of the conditions in paragraphs (a)(1) through (3) of this section exist:

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)