

---

## 40 C.F.R. § 63.7322

---

### What test methods and other procedures must I use to demonstrate initial compliance with the emission limits for particulate matter?

---

- (a) You must conduct each performance test that applies to your affected source according to the requirements in paragraph (b) of this section.
- (b) To determine compliance with the emission limit for particulate matter from a control device applied to pushing emissions where a cokeside shed is the capture system, follow the test methods and procedures in paragraphs (b)(1) and (2) of this section. To determine compliance with a process-weighted mass rate of particulate matter (lb/ton of coke) from a control device applied to pushing emissions where a cokeside shed is not used, follow the test methods and procedures in paragraphs (b)(1) through (4) of this section.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)