

40 C.F.R. § 63.7747

How do I apply for alternative monitoring requirements for a continuous emissions monitoring system?

- (a) You may request an alternative monitoring method to demonstrate compliance with the VOHAP emissions limits in § 63.7690(a)(10) for automated pallet cooling lines or automated shakeout lines at a new iron and steel foundry according to the procedures in this section.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)