
40 C.F.R. § 63.7898

How do I demonstrate continuous compliance with the emissions limitations and work practice standards for tanks?

- (a) You must demonstrate continuous compliance with the emissions limitations and work practice standards in § 63.7895 applicable to your affected tanks by meeting the requirements in paragraphs (b) through (d) of this section.
- (b) You must demonstrate continuous compliance with the requirement to determine the applicable tank control level specified in § 63.7895(b) for each affected tank by meeting the requirements in paragraphs (b)(1) through (3) of this section.
- (1) Keeping records of the tank design capacity according to the requirements in § 63.1065(a).
- (2) For tanks subject to § 63.7886(b)(1)(ii) and not using Tank Level 2 controls, meeting the requirements in paragraphs (b)(2)(i) and (ii) of this section.
- (i) Keeping records of the maximum HAP vapor pressure determined according to the procedures in § 63.7944 for the remediation material placed in each affected tank.
- (ii) Performing a new determination of the maximum HAP vapor pressure whenever changes to the remediation material managed in the tank could potentially cause the maximum HAP vapor pressure to increase to a level that is equal to or greater than the maximum HAP vapor pressure for the tank design capacity specified in Table 2. You must keep records of each determination.
- (3) Keeping records to document compliance with the requirements of this subpart according to the requirements in § 63.7952.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)