

## 40 C.F.R. § 63.8810

---

### How do I monitor and collect data to demonstrate continuous compliance?

---

- (a) If you own or operate a loop slitter adhesive use affected source, you must meet the requirements in paragraphs (a)(1) and (2) of this section.
- (1) Maintain a list of each adhesive and the manufacturer or supplier of each.
- (2) Maintain a record of EPA Method 311 (appendix A to 40 CFR part 63), approved alternative method, or other reasonable means of HAP content determinations indicating the mass percent of each HAP for each adhesive.
- (b) If you own or operate a flame lamination affected source, you must meet the requirements in paragraphs (b)(1) through (3) of this section if you use a scrubber, or paragraph (b)(4) of this section if you use any other control device.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)