

## 40 C.F.R. § 63.9633

---

### How do I monitor and collect data to demonstrate continuous compliance?

---

- (a) Except for monitoring malfunctions, out of control periods, associated repairs, and required quality assurance or control activities (including as applicable, calibration checks and required zero and span adjustments), you must monitor continuously (or collect data at all required intervals) at all times an affected source is operating.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)