

40 C.F.R. § 63.9635

How do I demonstrate continuous compliance with the work practice standards that apply to me?

- (a) You must demonstrate continuous compliance with the work practice standard requirements in § 63.9591 by operating in accordance with your fugitive dust emissions control plan at all times.

This document is only available to subscribers. Please log in or purchase access.

[Purchase Login](#)