

## 29 C.F.R. § 1926.354

---

### Welding, cutting, and heating in way of preservative coatings.

---

- (a) Before welding, cutting, or heating is commenced on any surface covered by a preservative coating whose flammability is not known, a test shall be made by a competent person to determine its flammability. Preservative coatings shall be considered to be highly flammable when scrapings burn with extreme rapidity.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)