

## 40 C.F.R. § 52.533

---

### Source surveillance.

---

The plan lacks test methods for several source categories. As required by § 52.12(c)(1) of this part, EPA test methods (found at 40 CFR part 60) will be used by EPA to determine compliance with the following emission limiting standards:

This document is only available to subscribers. Please log in or purchase access.

[Purchase Login](#)