

40 C.F.R. § 60.165

Monitoring of operations.

- (a) The owner or operator of any primary copper smelter subject to § 60.163 (b) shall keep a monthly record of the total smelter charge and the weight percent (dry basis) of arsenic, antimony, lead and zinc contained in this charge. The analytical methods and procedures employed to determine the weight of the total smelter charge and the weight percent of arsenic, antimony, lead and zinc shall be approved by the Administrator and shall be accurate to within plus or minus ten percent.
- (b) The owner or operator of any primary copper smelter subject to the provisions of this subpart shall install and operate:
- (1) A continuous monitoring system to monitor and record the opacity of gases discharged into the atmosphere from any dryer. The span of this system shall be set at 80 to 100 percent opacity.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)