

40 C.F.R. § 60.3044

Is there a minimum amount of operating parameter monitoring data I must obtain?

- (a) Except for monitor malfunctions, associated repairs, and required quality assurance or quality control activities (including, as applicable, calibration checks and required zero and span adjustments of the monitoring system), you must conduct all monitoring at all times the OSWI unit is operating.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)