

40 C.F.R. § 1042.325

What happens if an engine family fails the production-line testing requirements?

- (a) We may suspend your certificate of conformity for an engine family if it fails under § 1042.315. The suspension may apply to all facilities producing engines from an engine family, even if you find noncompliant engines only at one facility.
- (b) We will tell you in writing if we suspend your certificate in whole or in part. We will not suspend a certificate until at least 15 days after the engine family fails as described in § 1042.315(b). The suspension is effective when you receive our notice.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)