

## 40 C.F.R. § 1065.215

## Pressure transducers, temperature sensors, and dewpoint sensors.

- (a) Application. Use instruments as specified in this section to measure pressure, temperature, and dewpoint.
- (b) Component requirements. We recommend that you use pressure transducers, temperature sensors, and dewpoint sensors that meet the specifications in Table 1 of § 1065.205. Note that your overall systems for measuring pressure, temperature, and dewpoint must meet the calibration and verifications in § 1065.315.

This document is only available to subscribers. Please  $\log$  in or purchase access.

Purchase Login