

40 C.F.R. § 1065.790

Mass standards.

- (a) *PM balance calibration weights.* Use PM balance calibration weights that are certified as NIST-traceable within $\pm 0.1\%$ uncertainty. Make sure your highest calibration weight has no more than ten times the mass of an unused PM-sample medium.

This document is only available to subscribers. Please log in or purchase access.

[Purchase Login](#)