

40 C.F.R. § 761.250

Sample site selection for pipeline section abandonment.

This procedure is for the sample site selection for a pipeline section to be abandoned, in accordance with $\{61.60(b)(5)(i)(B).$

- (a) *General.* (1) Select sample collection sites in the pipeline section(s) by following the directions in paragraph (b) of this section.
- (2) Select the proper sampling position along the pipe by following the directions in § 761.247 (c) and (d).
- (3) Assure, by visual inspection, the absence of free-flowing liquids in the pipe by affirming no liquids at all liquid collection points and all ends of the pipeline section to be abandoned.

This document is only available to subscribers. Please log in or purchase access.

Purchase Login