

## 40 C.F.R. § 264.347

---

### Monitoring and inspections.

---

(a) The owner or operator must conduct, as a minimum, the following monitoring while incinerating hazardous waste:

- (1) Combustion temperature, waste feed rate, and the indicator of combustion gas velocity specified in the facility permit must be monitored on a continuous basis.
- (2) CO must be monitored on a continuous basis at a point in the incinerator downstream of the combustion zone and prior to release to the atmosphere.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)