

## 40 C.F.R. § 98.395

---

### Procedures for estimating missing data.

---

(a) *Determination of quantity.* Whenever the quality assurance procedures in § 98.394(a) cannot be followed to measure the quantity of one or more petroleum products, natural gas liquids, types of biomass, feedstocks, or crude oil during any period (e.g., if a meter malfunctions), the following missing data procedures shall be used:

This document is only available to subscribers. Please log in or purchase access.

[Purchase Login](#)