

40 C.F.R. § 63.10896

What are my operation and maintenance requirements?

- (a) You must prepare and operate at all times according to a written operation and maintenance (O&M) plan for each control device for an emissions source subject to a PM, metal HAP, or opacity emissions limit in § 63.10895. You must maintain a copy of the O&M plan at the facility and make it available for review upon request. At a minimum, each plan must contain the following information:

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)