

40 C.F.R. § 63.1185

How do I establish the average operating temperature of an incinerator?

(a) During the performance test, you must establish the average operating temperature of an incinerator as follows:

- (1) Continuously measure the operating temperature of the incinerator.
- (2) Determine and record the average temperatures in consecutive 15-minute blocks.

This document is only available to subscribers. Please log in or purchase access.

[Purchase Login](#)