

## 40 C.F.R. § 63.5190

## What records must I maintain?

- (a) You must maintain the records specified in paragraphs (a) and (b) of this section in accordance with § 63.10(b)(1):
- (1) Records of the coating lines on which you used each compliance option and the time periods (beginning and ending dates and times) you used each option.
- (2) Records specified in  $\S$  63.10(b)(2) of all measurements needed to demonstrate compliance with this subpart, including:
- (i) Continuous emission monitor data in accordance with § 63.5150(a)(2);
- (ii) Control device and capture system operating parameter data in accordance with § 63.5150(a)(1), (3), and (4);
- (iii) Organic HAP content data for the purpose of demonstrating compliance in accordance with § 63.5160(b);

This document is only available to subscribers. Please log in or purchase access.

Purchase Login