

40 C.F.R. § 63.5880

How do I determine how much neat resin plus is applied to the line and how much neat gel coat plus is applied to the line for continuous lamination/casting operations?

Use the following procedures to determine how much neat resin plus and neat gel coat plus is applied to the line each year.

- (a) Track formula usage by end product/thickness combinations.

This document is only available to subscribers. Please log in or purchase access.

[Purchase Login](#)