

40 C.F.R. § 63.6003

How do I monitor and collect data to demonstrate continuous compliance with the emission limits for tire production affected sources?

- (a) You must monitor and collect data as specified in Table 9 to this subpart.
- (b) Except for periods of monitoring malfunctions, associated repairs, and required quality assurance or control activities (including, as applicable, calibration checks and required zero and span adjustments), you must monitor continuously (or collect data at all required intervals) while the affected source is operating. This includes periods of startup, shutdown, and malfunction when the affected source is operating.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)