

## 40 C.F.R. § 63.7324

---

### What procedures must I use to demonstrate initial compliance with the opacity limits?

---

- (a) You must conduct each performance test that applies to your affected source according to the requirements in paragraph (b) of this section.
- (b) To determine compliance with the daily average opacity limit for stacks of 15 percent for a by-product coke oven battery on a normal coking cycle or 20 percent for a by-product coke oven battery on batterywide extended coking, follow the test methods and procedures in paragraphs (b)(1) through (3) of this section.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)