

40 C.F.R. § 63.7743

How do I demonstrate continuous compliance with the emissions limitations that apply to me?

- (a) You must demonstrate continuous compliance by meeting the applicable conditions in paragraphs (a)(1) through (12) of this section. When alternative emissions limitations are provided for a given emissions source, you must comply with the alternative emissions limitation most recently selected as your compliance alternative.
- (1) For each electric arc metal melting furnace, electric induction metal melting furnace, or scrap preheater at an existing iron and steel foundry,
- (i) Maintaining the average PM concentration in the exhaust stream at or below 0.005 gr/dscf; or
- (ii) Maintaining the average total metal HAP concentration in the exhaust stream at or below 0.0004 gr/dscf.
 - (2) For each cupola metal melting furnace at an existing iron and steel foundry,
- (i) Maintaining the average PM concentration in the exhaust stream at or below 0.006 gr/dscf; or
- (ii) Maintaining the average total metal HAP concentration in the exhaust stream at or below 0.0005 gr/dscf; or
- (iii) Maintaining the average PM mass emissions rate at or below 0.10 pound of PM per ton (lb/ton) of metal charged; or
- (iv) Maintaining the average total metal HAP mass emissions rate at or below 0.008 pound of total metal HAP per ton (lb/ton) of metal charged.
 - (3) For each cupola metal melting furnace or electric arc metal melting furnace at new iron and steel foundry,
 - (i) Maintaining the average PM concentration in the exhaust stream at or below 0.002 gr/dscf; or
- (ii) Maintaining the average total metal HAP concentration in the exhaust stream at or below 0.0002 gr/dscf.
 - (4) For each electric induction metal melting furnace or scrap preheater at a new iron and steel foundry,
- (i) Maintaining the average PM concentration in the exhaust stream at or below 0.001 gr/dscf; or
- (ii) Maintaining the average total metal HAP concentration in the exhaust stream at or below 0.00008 gr/dscf.

This document is only available to subscribers. Please log in or purchase access.

Purchase Login